



Contents Listing

MGB Workshop Notes

Introducing The....

MG Car Club

Membership Includes.....

-  Subscription to our award winning 100 page Club magazine
-  Free Technical Help
-  Discounts on Insurance
-  Discounts on Tickets
-  Discounts on Spares
-  Hundreds of annual events
-  Quality MG Merchandise
-  Affiliated Clubs Worldwide
-  7 Race Championships
-  A great social life!



Why You Should Join Us.

Founded in 1930 we have the experience and know how to help you make the most of owning and running an MG. Activities are organised for all age groups, tastes and models of MG. Social meets, touring, technical seminars, autotests, hill climbs and race meetings!

01235 555552

www.mgcc.com



MGB Workshop Notes

MGB Register

The MGB Register welcomes all enthusiasts with MGB and MGBGT models. The key strengths of the MGB Register are:

- **MGB Register website**
An active website with news, information on an active programme of events, a useful discussion forum, an MGB Shop with a popular clothing range, cars for sale adverts, an eNewsletter and Te
- **Programme of events** organised by the MGB Register each year including a Spring Run, an annual Weekend Event, an MGB Maintenance and Rolling Road weekend and an annual MGB Lecture. The MGB Register has always been a particularly sociable group with regular gatherings at MG Car Club meetings, particularly at the Club's annual International MG Meeting at Silverstone.
- **MGB Workshop Notes** - a series of useful spares and service tips and information.

With these strengths and essential support, the MGB Register is certainly the specialist group any MGB or MGBGT enthusiast should join. From its formation in the late 1970s, the MGB Register has attracted large numbers of MGB enthusiasts and continues to grow strongly today with members in the UK and overseas.

Joining the MGB Register

Joining the MGB Register is very straightforward – there is an easy to use online registration form at <http://www.mgb-register.org> or you can obtain a form from Club Office or from the MGB Registrar and mail it to the MGB Registrar, MG Car Club, Kimber House, PO Box 251, Abingdon on Thames, Oxfordshire OX14 1FF

MG Car Club

If you are an MG enthusiast then here is the MG Club for you. We welcome enthusiasts for all models of the famous marque – from machines like the current MGF and recent MG RV8 bearing the famous Octagon to modern BCV8 classics, Midgets, MGAs and back to the T-types and those pre-war models that created the legend that is MG!

The MG Car Club has a regular award winning monthly magazine called **Safety Fast!**, active Registers providing technical support and spares help for each MG model, spares specialists, insurance schemes for MGs and of course some of the best club motor sport and competition events – all within a wide and comprehensive social network in the UK, Mainland Europe and overseas. In all the MG Car Club has around 30,000 members Worldwide.

The MG Car Club, founded with factory support and encouragement in 1930, is run by enthusiasts for enthusiasts. We maintain our close association the old factory with our Club Office in Cemetery Road in Abingdon adjacent to Larkhill House, the former administrative building at the MG plant. The MG Car Club is run in the true spirit of a members' motor club and each member can participate in the activities and the running of the Club. It is company limited by guarantee.

Joining the MG Car Club

If you are not a member of the MG Car Club, full

membership details and a new member pack can be obtained from the Club's office in Abingdon, the home of MG. Just contact:

MG Car Club
Kimber House
PO Box 251
Abingdon on Thames
Oxfordshire OX14 1FF
Tel: 01235 555552
mgcc@mgcc.co.uk
www.mgcc.co.uk

The Club Office team will be pleased to hear from you and welcome you as a member of the MG Car Club – the Marque of Friendship!

Why not join now!



Cover photo: An MGB Roadster in Tartan Red with an LED sidelight bulb upgrade. (Photo: Victor Smith)

MGB Workshop Notes Series

The MGB Workshop Notes series is based on the successful V8 Workshop Notes series we started in early 1979 together with additional notes contributed by MGB enthusiasts. The V8 Register has produced the MGB Workshop Notes series for MGB enthusiasts as a source of useful information on servicing MGBs and sourcing spare parts.

Shortly after the formation of the V8 Register in 1978, the V8 Workshop Notes series was launched to help members maintain this limited production model and source spares. Victor Smith, the founder of the V8 Register, took on the role of editing the series and encouraging contributions from members of the V8 Register. Many individual notes were published in the V8 Register column in *Safety Fast!* - the award winning monthly magazine of the MG Car Club - but as the number of notes grew rapidly, the series was published as individual volumes in a convenient A5 spiral bound layflat format.

The aims of the series are quite simple – they are to amplify or clarify the MGB Workshop Manual AKD3259 and to give tips on the availability of spares and service. The series has continued to thrive and is a popular source of information for fellow MGB enthusiasts.

Caution and Disclaimer

The V8 Register of the MG Car Club has published the articles contained herein in good faith. However, neither the MG Car Club, the V8 Register, the MGB Register or their officers, nor the respective authors, can accept legal responsibility for the accuracy of any of the statements contained herein. These articles are intended to supplement the official workshop manual and any other publications produced and/or supplied by MG and/or MG Rover and reference should be made to those publications. Accordingly the MG Car Club Limited, the V8 Register, the MGB Register and their officers and the authors of these articles hereby

MGB Workshop Notes

Contents Listing

Volume 1

- | | | | |
|---|----------------|--|-----------------|
| 1. Throttle cable – a caution | | | Peter Laidler |
| 2. Removing the relief valve on a V8 overdrive unit | Victor Smith | | Mick Westrop |
| 3. Handbook error – steering & suspension grease points | John Dupont | | Peter Laidler |
| 4. Drain plug washer (sump) & pressure relief valve | John Dupont | | Paul Busby |
| 5. Brake servo failure | John Dupont | | Jerry Bright |
| 6. Front wheel arch (see also Note 48) | Jeff Ward | | Mick Westrop |
| 7. Looking after your body! | Tom Studer | | Graham Freeman |
| 8. Continued body care! | Philip Morgan | | Chris Hall |
| 9. How to keep cool under pressure – V8 cooling system | Colin Leisk | | Jerry Bright |
| 10. More cooling tips | Jim Gibson | | Peter Laidler |
| 11. Even more cooling tips | Lothar Taverne | | Chris Hall |
| 12. Anti-theft device | Victor Smith | | David Yeo |
| 13. Cooling fan override switch | Philip Morgan | | Chris Bovington |
| 14. Sequel to the manual switch for cooling fans | Geoff Allen | | Peter Laidler |
| 15. Reverse gear jumps out? | Peter Laidler | | Geoff Seaton |
| 16. V8 alternator | Chris Hall | | Jerry Bright |
| 17. Delco Remy alternator malfunction | Steve Foldhazy | | Mick Westrop |
| 18. V8 alternator – another sequel
(abstract from notes) | | | Bill Burrige |
| 19. Exhaust corrosion tip | Peter Laidler | | Geoff Seaton |
| 20. Ballast resistance ignition system | John Dupont | | John Dupont |
| 21. Saving your petrol tank from corrosion | Jerry Bright | | John Dupont |
| 22. Overdrive unit malfunction | Chris Hall | | Graham Freeman |
| 23. Leaking vacuum advance diaphragm | Chris Hall | | Paul Busby |
| 24. Interchangeability of MGBV8 and Rover parts
(Part 1) | Peter Laidler | | Peter Laidler |
| 25. Inter-changeability of parts (Part 2) | Peter Laidler | | Chris Bovington |
| 26. Front suspension modification | Peter Laidler | | Anthony Tindale |
| 27. Better brakes for your MGB | Peter Laidler | | Chris Bovington |
| 28. Loss of sparks | Chris Hall | | DGS |
| 29. Improving the MGB's handling | Philip Morgan | | Anthony Tindale |
| 30. Front wing baffle extensions | Mick Westrop | | Chris Bovington |
| 31. Speedometer cable | Peter Laidler | | Aiden Bristow |
| 32. Brake servo – a servicing summary | | | |
| 33. A rust prevention tip | | | |
| 34. Cooling fan motor | | | |
| 35. Petrol tank modification | | | |
| 36. Battery revival | | | |
| 37. Clutch slave cylinder sequel | | | |
| 38. Is your clutch really worn out? | | | |
| 39. Back axle clonk | | | |
| 40. Replacing hydraulic brake pipes | | | |
| 41. Fuel tanks for the BGT | | | |
| 42. Rear silencer – an economy tip | | | |
| 43. Dog guard for BGT! | | | |
| 44. Petrol tank sequel | | | |
| 45. Chrome nuts under the bonnet? | | | |
| 46. Wiper motor fault | | | |
| 47. Prevention of seizure of nuts and bolts | | | |
| 48. Fitting new front wings | | | |
| 49. Magnetic sump nut | | | |
| 50. Mind the toasted fingers! | | | |
| 51. Fire hazard article | | | |
| 52. Steering rack | | | |
| 53. Alternator bolt tightening tip | | | |
| 54. Servo sequel | | | |
| 55. Front brake calliper overhaul | | | |
| 56. A small tip on speedo cable | | | |
| 57. Underbody corrosion | | | |
| 58. The steering rack – another exception to note | | | |
| 59. More on batteries | | | |
| 60. Rubber lock washers | | | |
| 61. Waxoyl treatment for an MGB or V8 | | | |
| 62. Adhesives for the car – a comprehensive note | | | |
| 63. LE or ST – revised bodywork for an MGB | | | |
| 64. Petrol tank sequel | | | |
| 65. Rear wash/wipe installation for an MGBGT | | | |
| 66. Brake servo sequel – more! | | | |

MGB Workshop Notes

- | | | | |
|---|-----------------|--|----------------------|
| 67. Valuation of MGs for insurance purposes | Peter Laidler | 98. Front spoilers for the MGB | Hayden Winn |
| 68. MG running on | Godfrey Joly | 99. Cleaning out your drain tubes | Ken Smith |
| 69. Wiring diagram layout for the new two plug and socket requirements for tow bars | Anthony Tindale | 100. Improve your handling- fit a rear anti-roll bar | Paul Busby |
| 70. Handbrake compensating lever | Victor Smith | 101. Overheating mystery | Jack Wilson |
| 71. Front spoiler sequel | Steve French | 102. Removing a windscreen from an MGBGT | Peter Laidler |
| 72. Take care - your balls may drop! | Steve French | 103. Telescopic front suspension conversion kit | Elwood von Seibold |
| 73. Jumping out of reverse – another sequel | Geoff Allen | 104. Alternator problems | Mike Breedon |
| 74. Laying up an MGB | Mick Westrop | 105. Alternative alternator | Jacques Millet |
| 75. Under bonnet sound deadening felt dropping | Geoff Seaton | 106. Easier access to spare wheel space | Jacques Millet |
| | Mick Westrop | 107. Heater control valve | Peter Laidler |
| | | 108. Wind noise reduction | N.N. Mason |
| | | 109. Brakes pulling | Don Bishop |
| | | 110. Spark plug tester | Simon Porlock |
| | | 111. An important safety check | Roger Parker |
| | | 112. Fire extinguishers for your MG | David Knowles |
| | | 113. Tyre aspect ratios | David Knowles |
| | | 114. Fitting an SD1 5 Speed gearbox | John Wilson |
| | | 115. Overhauling the heater valve | David Knowles |
| | | 116. Revival of sagging seats | Dave Wellings |
| | | 117. Rear head restraints for children | Dave Wellings |
| | | 118. Wiper blade replacements | Peter Beadle |
| | | 119. Protection against damp in storage | Tim Langan |
| | | 120. More protection against damp | David Knowles |
| | | 121. Pick those ratios! | Dave Wellings |
| | | 122. C-post liner clip | David Knowles |
| | | 123. Interchange of parts between the US spec MGBGT and the MGBGT V8 | Paul Kile |
| | | 124. Battery management | Bryan Ditchman |
| | | 125. Tips for attending the annual 24 heures du Mans | Victor Smith |
| | | 126. Dealing with a squeal from the front brakes | Gordon Hesketh-Jones |
| | | 127. Replacement gearboxes | Victor Smith |
| | | 128. MGBV8 gearbox, clutch and propshaft | Roger Parker |
| | | 129. Borg-Warner T-5 gearbox information | Bob Hyclak |
| | | 130. Dellow Automotive 5 speed gearbox | |

Volume 2

- | | |
|--|-------------------|
| 76. Clutch slave cylinder removal | Steve French |
| 77. Electronic water injection system | Anthony Tindale |
| 78. Changing exhaust manifold bolts | Mick Westrop |
| 79. Cigar lighter broken? | Steve French |
| 80. Lubricating oils | R.A. Wild |
| 81. Mounting badges on a rubber bumpered MG | Geoff Allen |
| 82. Supercharging for road or track | Mick Broad |
| 83. To claim or not to claim! | Alan Kingwell |
| 84. Suspension and handling problem solutions | Hayden Winn |
| 85. Tie rod ends | Ken Dodds |
| 86. Rust prevention tip | Ken Dodds |
| 87. Air conditioning cars | P. Manners |
| 88. Gear selection problems | Ken Dodds |
| 89. Changing clutch and brake master cylinders | Victor Smith |
| 90. Rust prevention – a further note | Anthony Wilkinson |
| 91. Worn lower king pin bush | Colin Light |
| 92. Waxoyling an MGB or MGBGT Part 1 | Roger Cooper |
| 93. Waxoyling an MGB or MGBGT Part 2 | Roger Cooper |
| 94. Fitting louvres in a bonnet | Simon Horlock |
| 95. Drain plug drips | Hayden Winn |
| 96. That dwell adjuster again! | John Coulson |
| 97. Stainless steel petrol tank | John Roslyn |

MGB Workshop Notes

131. Layup and storage concerns for the MGBV8 enthusiast
Kurt Schley
132. Battery lifter or carrier
Dave Wellings
133. Battery carriers or lifters, another source
Anon
134. Bonnet hinge alignment
Brian Jackson
135. Steering rack caution
Bryan Ditchman
136. Brake servo failure
Kevin Hallsworth
137. Silicone or mineral brake fluid for V8s?
Victor Smith
Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley
138. Brake Fluid - corrosion in the hydraulic systems
Georg Muller
139. Rear shock absorber link arm
Bryan Ditchman
140. Using fire extinguishers in cars
Andrew Brown
141. Cleaning a coffee stain from an RV8 soft top
David Lawler
142. Renovo soft top care products
Victor Smith
143. Speeding British drivers may lose their driving licence in France
Reprint of an article in the Times
144. SU fuel pump relocation
Peter Berry
145. Alternative fuel pumps
Howard Gosling
146. Relocating the fuel pump in the V8 boot space – a caution
Geoff Allen
147. Steering column bush renovation
James Strachan
148. Ride height and bumpers
Roger Parker
149. Trouble with the original “top hat” battery terminals
Victor Smith
150. Further thoughts on the fuel pump relocation topic
Roger Parker
- Volume 3**
151. Insurance for classic MGs
Victor Smith
152. Air intake mesh
Bryan Ditchman
153. Small steps & giant strides in the handling
Ken Drake
154. Rear shock absorbers for MGBV8s
Gordon Hesketh-Jones
155. Fitting an override switch on the cooling fans
Ian Thomson
156. Fitting a 12 volt battery to a chrome bumpered MGBGTV8
Gordon Hesketh-Jones
157. Fault with the distributor vacuum unit
Geoff Hall
158. Engine cooling tip for the MGBGTV8
Bob Mason
159. Front shock absorbers on the MGBGTV8
Simon Pickford & Roger Parker
160. Rising tickover in hot conditions
Geoff Hall
161. Have you got a screw loose?
Bryan Ditchman
162. Options when faced with an engine rebuild
Dave Wellings & Gordon Hesketh-Jones
163. Do we need to replace the tyres on our V8s before they are worn out?
Roger Parker & Norman Green
164. Door jamb switch operating the internal console light
Gordon Hesketh-Jones
165. Internal tailgate lamp
Gordon Hesketh-Jones
166. White smoke – a scary moment!
Dave Wellings
167. Temporary steering tip
Geoff Allen
168. Thatcham immobilisers
Richard Groves
169. RV8 filler cap for the MGBGTV8
Bryan Ditchman
170. Relocating the temperature/oil pressure gauge and adding a voltmeter
Gordon Hesketh-Jones
171. Solving the rusting wheel nuts!
Gordon Hesketh-Jones
172. What could that “clonk” noise be?
Ben Millard & V8 Website postings
173. Soft suspension on an MGBGT
Iain Hallifax & V8 Website postings
174. Webasto blowout!
Ben Millard & V8 Website postings
175. Overheating problems with an MGBGTV8
Andrew Edgerton-Smith & Victor Smith
176. Steering wheel locks
Ben Millard & V8 Bulletin Board postings
177. Recommended tyre supplier
Peter Kilmister
178. MGBGTV8 cooling and overheating concerns
Roger Parker
179. Cause of carburettor flooding
Dr Gavin Bailey
180. Getting an MGBGT registered in France
Franck Morand
181. New mobile phone law in the UK
Victor Smith
182. Winter wheels for the MGBGTV8
Dr Gavin Bailey
183. Radar detector, a necessary protection?
Victor Smith
184. Insurance for a V8 Roadster
Ray Cobley & Geoff King
185. Hoyle suspension upgrade kits – a step change in improved handling
Victor Smith & Geoff King
186. To lift or not to lift, that is the question
Gavin Bailey
187. Horn fault causing an MOT failure
Victor Smith
188. Another way of registering a V8 in France
Franck Morand

MGB Workshop Notes

189. A long hot night at the Le Mans Classic – in fact just a little too hot!
Franck Morand
190. Solving front brake squeal
Mike Russell
191. No longer a period of grace on motor insurance renewals
Victor Smith
192. MGBV8 conversion – from dream to reality
Geoff King
193. Another windstop that looks good and works well
Mike Simmonds
194. Fitting a “lights on” alarm to an MGBGT
Alan Turner
195. Upgrading the sealed beam units on an MGB
Steve Taylor
196. How do you open the bonnet when the release cable has snapped?
Geoff Allen
197. Lighting history and terminology
Bob Owen
198. 12 volt battery conversion
Victor Smith
199. Two 12 volt batteries in parallel
Fred Jenns
200. TE low brake fluid detector – a vital safety device for an MGBGT
Bob Owen
201. Fitting a TE Low Brake Fluid Sensor in easy stages
Victor Smith
202. Front brake problem
Gordon Hesketh-Jones
203. Solving a fuse box riddle
Tony Head
204. Leather gear lever gaiter, not rubber
Tony Head
205. Review of the B&G castor reduction kit
Chris Hunt Cooke & Victor Smith
206. Uprated heater on a V8
Gordon Hesketh-Jones
207. Space saver wheels for V8s
David Waterton
208. Care with doublesided tape fixings
Gavin Bailey
209. Storing a V8 over Winter
Postings from the V8BB
210. Fitting a “modern CD stacker” in a V8
David Boniface
211. Cibie headlamp upgrade
David Biddle
212. Front windscreen replacement on an MGB Roadster
Bill McCullough
213. Reducing heat from downunder!
John Hornabrook
214. Fitting an ultimate radiator to cool a V8
Jamie Trapp
215. MGB & MGBGT front brake upgrade
Geoff King
216. Another 12v battery conversion
Kai Knickmann
217. Refurbishing a Webasto sunshine roof
Bob Owen
218. Uprated suspension bushes
John Targett
219. Fitting a walnut dashboard
Barrie Franklin
220. Fitting an 065 12 volt battery in an MGBGTV8
Malcolm Venables
221. Experience with Spax shock absorbers
Andy Torode & Gordon Hesketh-Jones
222. Fitting anti-tramp bars to an MGBGTV8
Chris Armitage
223. Where can I get a clean pair of number plates?
Robert Crowson
224. Why is there a glimmer from my ignition warning light?
Nigel Melbert, Chris Hunt Cooke & Brian Moyse
225. Frustration with tracing and solving a starting problem
Dave Wellings

Volume 4

226. Essential spares when touring abroad
Geoff King, Bob Owen, Victor Smith, Jim Gibson, Rob Lewis, Rob Collier & Mike Lane
227. Solving a faulty handbrake
Barrie Jones
228. Common wiring faults
Barrie Jones
229. Horn contact repair
Mike Russell
230. Topping up the damper on an SU HIF
Victor Smith
231. Battery conversion cures a V8 hot start problem
Bob Owen
232. Refurbishing the bulkhead shelf
Clive Wagerfield
233. Brake systems and servos
Bob Owen
234. Caution with replacement tyres
Howard Gosling
235. Which brake fluid?
Bob Owen
236. On the rolling road at Aldon
Alan Rennie
237. Tyre sealants
Roger Parker & an AA note
238. Where can I get a touch up!
Angus Munro
239. Replacement plain rubber cooling hoses – a caution
Editor
240. Renovo's plastic screen polish works!
Angus Munro
241. Critical views on spacesaver wheels
Bulletin Board contributors
242. Repairing an overdrive switch fault
Barrie Jones
243. Refurbishing the seats on an MGBGT
Richard Searle
244. Fuel pump replacement options
Bob Owen
245. Lights-on alarm
Graham Cornford
246. Getting an MGBV8 registered in Belgium
Henri Malcorps
247. Concerns with antifreeze for classic MGs
Victor Smith

MGB Workshop Notes

248. Improving a standard MGBGT seat
Barrie Jones
249. Fitting an oil thermostat to an MGBV8
Ralph Coulson
250. What pressures do you use with modern tyres on an MGBV8?
Ron Gammons
251. Sourcing a fitting an upgraded aluminium radiator
Graham Cornford
252. How do you get the windscreen and rear window chrome inserts back into the rubber surround?
Dave Wellings and Pete Jevons
253. Fitting central locking to an MGBGTV8
Martin Ashby
254. Installing cruise control to an MGBV8
Ralph Coulson
255. Luggage racks for MGV8s
Chris Yates
256. Failed replacement rear brake adjuster
Barrie Jones
257. Workshop tips
Ian Ailes
258. Using Jubilee clips correctly and choosing the correct size
Ian Jennings
259. Solving malfunctions with a V8 overdrive
Victor Smith
260. Fitted luggage for an MGB
Peter Wallis and Ken Clayton
261. Caution with your bonnet catch
Malcolm Venables
262. Courtesy light upgrade
Jon Moulds
263. Power steering options review
Victor Smith
264. Gearbox trouble with a Factory V8 box
Nick Gray
265. Replacement distributor with a Pertronix Ignitor upgrade
Victor Smith
266. Dealing with parabolic springs winding up under torque
Michael Beswick
267. Replacement V8 clutch master cylinder
David Brown
268. Modification to avoid a failed bonnet catch
Ralph Coulson
269. Different rear panel joints on a Factory MGBGT
Stuart Ratcliff, Mike Howlett & Michael O'Leary
270. Failed MGB bonnet catch - an alternative solution
Jon Moulds
271. Essential bonnet lock & safety catch servicing for an MGB
Ralph Coulson
272. Overheating - it may be a tired radiator cap
Victor Smith
273. More on burnt out relays
Vic Todman
274. Cooling fans upgrade from Revotec
Victor Smith
275. Cleaning out the fresh air vent chamber drain tube
Victor Smith
276. Drop link failure
Alan McLean, Ron Gammons & Gordon Hesketh-Jones
277. Radiator pressure caps
Tony Lake
278. Solving a problem with an LH overdrive cycling in and out
Victor Smith
279. Fitting air-con to an MGBGTV8
Gordon Hesketh-Jones
280. Hoyle IRS for a V8 Roadster
Angus Munro & Mike Howlett
281. Inline fuse protection for the V8 overdrive
TechTorque article in Safety Fast!
282. Solving bad electrical contacts in the fuse box
Gordon Hesketh-Jones
283. Do MGBs need oil coolers?
Andrew Lord, Mike Howlett & Roger Parker
284. Replacing a faulty fuse box
Gordon Hesketh-Jones
285. MGBGTV8 horn bracket – an alternative part
Gordon Mallett
286. Tracing a puzzling misfire on a Factory MGBGTV8
Ian Ailes & Peter Beadle
287. A warning for tall people
Chris Hunt Cooke
288. Replacing a faulty horn
Victor Smith
289. Rear spring shackle
George Wilder
290. Head up display with overdrive at night
Victor Smith
291. LED lights conversion
Victor Smith
292. Non-LED daytime running lights on classic cars
Michael Bernhard
293. Curing a sticking carburettor float
Richard Withington
294. What are the key issues to consider when deciding whether to fit 175 or 185 tyres on an MGBGT
Victor Smith
295. Replacing the spring on the tailgate stay assembly
Mike Russell
296. Importance of the seemingly insignificant – breather pipes on an SU fuel pump
Peter Cook
297. Avoiding a fine for an incorrect registration plate
George Wilder
298. Getting an MGBGT that's been stored back on the road
Mike Howlett, Malcolm Venables, Bob Owen & Gavin Brown
299. Retrofitting daytime driving lights to a classic car
Vic Todman & Victor Smith
300. Dash cams – what are they like?
Victor Smith

MGB Workshop Notes

Volume 5

301. Replacing dashboard instrument bulbs with LEDs
Richard Withington & Nic Houslip
302. Check your antirollbar links
Nic Houslip
303. Where can you get replacement drop link?
Nic Houslip
304. Check your plastic breather pipe is not missing from your back axle
Derek Squires
305. Fault with the Starter 6RA relay
Steve Newton
306. How does a 6RA relay work?
Nic Houslip
307. Steering wheel centre colour
Timothy Southall
308. Thread compatibility with replacement back axle breathers
V8BB
309. Replacing the HIF6 floats
Victor Smith
310. Solving an alternator problem
Nic Houslip
311. How to connect up a battery conditioner to an MGB
Nic Houslip
312. Stubborn Stalks
Nic Houslip
313. How to clean your MGB to almost concours condition
Howard Guiney
314. Collapsible steering column
Mike Macartney
315. MGB windscreen quarter light seal replacement
Mike Maude-Roxby
316. What's happened to "Ted's Knob"?
Nic Houslip & Victor Smith
317. Refitting Ted's knob
Nic Houslip
318. Gas struts for an MGBGTV8 luggage platform
David Worthington
319. Why does a starter motor not turn over?
Nic Houslip
320. How can I stop my brakes squeal?
Angus Munro
321. Ever broken a stud removing parts from your engine?
Nic Houslip
322. Dual circuit brake servo upgrade
Mike Howlett
323. Fitting instructions for Smiths Industries' supplementary instruments
Keith Belcher
324. Changing the differential thrust washers
Dugald MacNeill
325. Clip on the damper in an HIF carburettor
Keith Belcher & Nic Houslip
326. Basic windscreen wiper maintenance
Nic Houslip
327. What oil for the V8 gearbox?
David Halliday
328. Motorola radio fitting instructions
Peter Beadle
329. MGBGTV8 overdrive failure solved
Andy Goves
330. Internal door handle not operating?
David Beatty
331. Finding replacement sunvisors for an MGBGTV8
Peter Beadle
332. Jubilee MGBGTV8s
Peter Beadle & Rob Grieves
333. Rear parking sensor for a rubber bumper MGB
John Gay
334. Take care of your steering column
Nic Houslip
335. Refurbishing an MGBGTV8 steering wheel
David Hamm
336. Finding parts for a Hardtop for an MGB Roadster
Peter Nixon
337. Surprise on opening up an MGB back axle
Peter Nixon
338. Corrosion in the cills
Editor
339. Keep your back axle breather clear to avoid moisture build up Next
Ralph Hardwick
340. Daytime lighting options for classics
Victor Smith
341. Replacement 7" H4 headlamps for the original sealed beams
Chris Bound, Mike Howlett, Chris Hunt Cooke & Peter Spurrs
342. Installing DRLs in replacement H4 Halogen MGB headlamps
Chris Bond, Chris Hunt Cooke, Nic Houslip and Tony Lake
343. Concerns with the relative visibility of classic cars
Victor Smith
344. MGBGTV8 halogen headlamp conversion with relays
Peter Spurrs
345. Which bulb for a replacement H4 headlamp
Chris Hunt Cooke
346. Using relays in a classic car
Chris Hunt Cooke & Editor
347. Another H4 headlamp upgrade with DRLs
Roger Parker
348. Are LED headlight upgrades legal in the UK?
Chris Hunt Cooke
349. Fitting a Moss headlamp relays kit
Andy Goves
350. Solving ignition problems
Peter Spurrs

Volume 6

351. Installing headlamp relays kit
Richard Withington & Nic Houslip
352. Identifying original sealed beam headlights
Nic Houslip
353. Bleeding your brakes with an Eezibleed kit
Barrie Jones
354. Fitting a battery master switch
Chris Bound
355. Refurbishing the ashtray
Peter Spurrs
356. Revitalising the paintwork on an MGB
Peter Spurrs
357. Fitting power steering to an MGB
Jim Livingstone
358. Overhauling an MGB fusebox
Jim Livingstone
359. Overhauling the steering rack on an MGB
Jim Livingstone

MGB Workshop Notes

360. Next Note

Editor

The MGB Workshop Notes series continues