



Index

This is a **complete Index to the whole MGB Workshop Notes series** which will enable members to look up topics and find where they have been covered in the series. The Index is regularly updated as new workshop notes are provided by members and added to the series. From time to time members may decide they want an Update Set of MGB Workshop Notes so they can obtain the additional workshop notes. For full details of how to get an Update Set please visit our Online Shop.

Topic	Note	Vol
1. ENGINE		
Accelerator cable	1	1
Ballast resistance, ignition	20	1
	350	5
Broken stud removal	323	5
Chrome nuts under bonnet	45	1
Distributor, advance fault	157	1
Exhaust		
- corrosion tip	19	1
Exhaust manifolds		
- bolts, changing	78	2
- economy tip	42	1
Inlet manifold		
- gasket	72	2
Interchangeability of parts	24	1
	25	1
	123	2
Jubilee clips, correct use	258	4
Lubricating oils	80	2
Misfire, puzzling	350	5
Oil coolers, are they needed?	283	4
Oil thermostat modification	249	4
Rebuild options, engine	162	3
Rolling road, tuning	236	4
Running on	68	1
Spark plug tester	110	2
Speedometer cable	31	1
Starting problems	149	2

Index to the whole series

Starter motor		
- fault, does not turn over	320	5
- fault found and cured	225	4
- hot start problem cure	231	4
- slow starter cure	231	4
Stud, broken removal	323	5
Sump drain plug		
- compressible washer	4	1
- drip tip	95	2
- magnetic	49	1
Supercharging	82	2
Throttle cable caution	1	1
Tickover, rising in hot weather	160	3
Vacuum advance diaphragm	23	1
Water injection	77	2

2. IGNITION SYSTEM

Ballast resistance system	20	1
	350	5
Battery isolator switch	354	6
Battery terminal fault	225	4
Distributor, advance fault	157	3
Distributor with Pertronix	265	4
Dwell meter	149	2
Dwell adjuster	96	2
- Pertronix conversion	265	4
High tension leads	68	2
Spark plug tester	110	2
Sparks, loss	28	1
Starting gremlins	149	2
Throttle cable	1	1
Vacuum unit, distributor	157	3
Warning light glimmer	224	4

3. COOLING SYSTEM

Antifreeze	9	1
Antifreeze concerns	247	4
Bonnet louvres	158	3
Cooling fans		
- blades	155	3
- iolite washer	9	1
- override switch	13	1
	14	1
	155	3
Cooling issues	158	3
	178	3
- upgrade kit	274	4
- Revotec twin fan upgrade kit	274	4
Cooling improvements	155	3
	158	3
	175	3
	178	3
	213	4
	214	4
Cooling tips	9	1
	10	1
	11	1
Expansion tank		
- do not overfill!	175	3
- hose, replacement	189	3
Fans	155	3
Flushing out	178	3
Heater, additional cooling!	155	3
Heater control valve	107	2
	115	2
- Converting	107	2

MGB Workshop Notes

- Overhauling the valve	115	2
Heater hose		
- BHH1038 splits, care	169	3
- Jubilee clips, correct use	258	4
- note	9	1
- plain rubber hoses, a caution	239	4
Heater matrix, upgrade	158	3
Improved cooling	178	3
Jubilee clips, correct use	258	4
Oil thermostat modification	249	4
Otter switch	9	1
Overheating mystery	101	2
Overheating	155	3
	175	3
	178	3
Override switch for fans	155	3
	158	3
	178	3
Pressure cap replacement	277	4
Pressure system	9	1
Radiator		
- aluminium replacement	214	4
- 4 core replacement	158	3
- cap, replacement	277	4
'- pressure cap replacement	277	4
- replacement	251	4
- uprated unit	158	3
**	399	11
Replacement		
- Pressure cap replacement	277	4
- radiator	251	4
Thermostat, modification	155	3
	178	3
Water pump		
- overheating	101	2
4. FUEL SYSTEM		
Accelerator cable		
- caution	1	1
Balls may drop	72	1
Bendix fuel pump	145	2
Carburettors		
- damper clip.HIF	327	5
- dampers, topping up	234	4
- float sicking	293	4
- flooding, possible cause	179	3
- interconnection tube	51	1
	86	2
	179	3
- replacing HIF6 floats	309	5
Cruise control retrofit	254	4
Diaphragm (advance), leak	23	1
Fuel filler cap, replacement	169	3
Fuel pump		
- alternative	145	2
- electronic fuel pump	244	4
- Jubilee clip caution	258	4
- Jubilee clips, correct use	258	4
- lay-up concern	131	2
- relocation	144	2
	145	2
	146	2
	150	2
- replacement options	244	4
Lay-up difficulty, fuel		
- Fuel deterioration	131	2

Index to the whole series

- Fuel pump, SU	131	2
Facet fuel pumps	244	4
Fuel tank		
- baffle plate, filling	44	1
- corrosion treatment	21	1
- Explosafe	35	1
- protecting a new tank	44	1
- sequel	64	1
- stainless steel replacement	97	2
- fire hazard	51	1
Petrol, deterioration	131	2
Petrol tank		
- baffle plate, filling	44	1
- Explosafe	35	1
- protecting a new tank	44	1
- sequel	64	1
- stainless steel replacement	97	2
	150	2
5. CLUTCH		
Clutch release problems	128	2
Lay-up difficulties	130	2
Master cylinder		
- changing	89	2
Slave cylinder		
- removal	76	2
- sequel	37	1
Wear, clutch	38	1
6. GEARBOX		
Bellhousing, TVR	127	2
Borg-Warner T-5	127	2
- options	128	2
	129	2
	130	2
- speedometer	128	2
Cracks, hairline in casing	264	4
Costello 5 speed gearbox	127	2
Dellow Automotive box		
- Conversion kit	130	2
- Replacement option	130	2
Final drive ratio	121	2
Gear selection problems	88	2
	292	4
Hairline crack in casing	264	4
Lubricating oils	56	1
	80	1
	329	5
Master cylinder replacement	267	4
Overdrive cycling in and out	278	4
Overdrive, head up display	290	4
Overdrive, inline fuse	281	4
Overdrive on reminder light	290	4
Overdrive malfunctions	22	1
	33	1
	259	4
	331	5
Overdrive relief valve	22	1
Overdrive, restoring option on		
3 rd gear	278	4
Ratios	121	2
Replacement gearbox		
- Borg-Warner T-4	129	2
- Borg-Warner T-5	129	2
- Clutch choice	127	2
- Costello 5 speed box	127	2
- Crossmember	127	2
- Dellow Autom've box	129	2

MGB Workshop Notes

- Dellow conversion kit	129	2
- Options, replacement	126	2
- LT77 (SD1 box)	126	2
- R380	126	2
Reverse jumps out	15	1
	38	1
	279	8
SD1 gearbox		
- alternative gearbox	127	2
- fitting an SD1 box	114	2
Speedometer cable	31	1
Welding cracked casing	264	4
7. PROPSHAFT		
GKN Driveline	128	2
Replacement gearbox	128	2
Universal joints	172	3
8. REAR AXLE		
Anti-tramp bars, fitting	222	4
Breather check "Plastic"		
- "Plastic" check	304	5
- Thread compatibility	308	5
Breather, keep clear	339	5
"Clonk" from back axle	39	1
	172	3
Cross pin		
- fault	39	1
Differential, thrust washers	326	5
	337	5
Hoyle suspension upgrade	185	3
Lubricating oils	80	2
Planet wheels		
- essential check	39	1
Propshaft UJs	172	3
Thrust washers, differential	326	5
Universal joints	172	3
Upgrade kit – Hoyle Eng	185	3
9. REAR SUSPENSION		
Alternative shock absorbers	153	3
Anti-roll bar, rear		
- note	84	2
	153	3
- fitting	100	2
Anti-tramp bars, fitting	222	4
Breather, plastic replacement	304	5
	308	5
Brost, spring treatment	266	4
Bushes, upgraded	218	3
Handling		
- improving	29	1
	100	2
- upgrade	135	3
Hoyle suspension upgrade	185	3
Hoyle experience	280	4
Independent rear upgrade	185	3
Link arm, rear shocker	139	2
Lowering an MGBGT	84	2
Parabolic springs	266	4
Rear spring shackle caution	289	4
Rear shock absorbers		
- Bilstein	154	3
- Don Hayter's notes	154	3
- Konis	154	3
- lever arm	154	3
- link arm	139	2
- replacement alternatives	154	3

Index to the whole series

- Spax	154	3
Replacement rear springs	222	4
Ride height & bumpers	148	2
Ron Hopkinson handling kit	153	3
Shackle, rear spring caution	289	4
Shock absorber, alternatives		
- alternatives	154	2
- performance	154	2
Spax experiences	221	4
Springs, retempering	84	2
10. INSURANCE		
Agreed value	151	2
Classic car insurance	151	2
Claims, county court route	83	2
Conversions - insurance	184	3
Limited mileage policies	151	2
Mobile phone, new law	181	3
Renewals, no grace period	191	3
Reinstatement cost	151	2
Thattham, insurers' requ'ts	168	3
Upgrade kit – Hoyle Eng	185	3
Valuations	67	2
	151	2
11. STEERING		
Castor angle reduction kit	205	3
EPAS EZ upgrade	357	6
Fire risk, horn wiring	189	3
Grease nipples		
- handbook error	3	1
- three not two	3	1
Overhaul, steering rack	359	6
Power steering options	263	4
Power steering EZ upgrade	357	6
Spring modifications	266	4
Steering column		
- bush renovation	147	2
- collapsible	314	5
Steering rack		
- caution	135	2
- bracket on cross member	135	2
- exception to note	58	1
- seized mounting bolts	52	1
Temporary steering tip	167	3
Wheel (steering) centre colour	307	5
12. FRONT SUSPENSION		
Anti-roll bar, front		
- uprated bar	29	1
Bushes, metal inserts	29	1
Castor angle reduction	205	3
Drop Link		
- check	302	5
- failure	276	4
- replacement parts	303	5
Grease nipples		
- handbook error	3	1
- three not two nipples!	3	1
Handling improvements		
- improving	29	1
- upgrade	153	3
Hoyle suspension upgrade	185	3
Hoyle upgrade experience	280	4
King pins		
- distance tube	26	1
Lowering an MGBGT	84	2

MGB Workshop Notes

Moss Dynamic Suspension System	155	3
Performance Suspension System, BMHE	153	3
Ride height & bumpers	148	3
Reconditioned shockers	159	3
RV8 drop link replacement	276	4
Shock absorbers		
- remove & refit	26	1
- replacements	159	3
- reconditioned quality	159	3
Soft front suspension	173	3
Spax, telescopics		
- conversion	100	2
- telescopics	159	2
Steering column, care	334	5
Track rods ends, releasing	85	2
Upgrade kit – Hoyle Eng	185	2
13. BRAKES		
Adjuster, fault rear	256	3
Anti squeal kit	126	2
	321	5
Bleeding brakes, Eezibleed	353	6
Brake calliper	126	2
Brake fluid, which one?	235	4
Brakes pulling	109	2
Brake shims	126	2
Brake servo failures		
- air valve piston leaks	136	2
- cracked vacuum piston	136	2
- failures, important notes	136	2
- low brake fluid sensor	200	3
- LBFS detailed fitting guide	201	3
- seal failure	136	2
- servicing summary	32	1
- sequel	54	1
	66	1
Brake squeal cure (front)	190	3
Cementite explained	202	3
Compensating lever	70	2
Discs		
- cooling	27	1
- drilled	27	1
- warn discs	109	2
Dual circuit servo upgrade	324	5
Front brake callipers		
- anti-squeal kit	126	2
- overhaul	55	1
- squeal	126	2
	190	2
	322	5
- upgrade	215	3
Glycol brake fluid choice	235	4
Handbrake, compensating lever	70	2
Handbrake fault, solving	227	4
Hydraulic pipe replacement	40	1
Master cylinder, change	89	2
Front pads, replacements	202	3
Pulling brakes	109	2
Rear brake adjuster, faulty replacement	256	4
Servo		
- air valve piston leak	136	2
- brake servos & systems	233	4
- cracked vacuum piston	136	2

Index to the whole series

- failures, important notes	5	1
	136	2
- low brake fluid sensor	200	3
- overhaul kit	32	1
- replacement	136	2
- seal failure	136	2
	233	4
- sequel	54	1
	66	2
Silicone brake fluid	137	2
	138	2
14. ELECTRICAL EQUIPMENT		
Alternator		
- alternative alternators	105	2
- bolt tightening sequence	53	1
- Bosch alternative	105	2
- problems	104	2
- pulley retaining nut	104	2
- solving a problem	310	5
Battery		
- alternative battery	59	2
- caution	156	3
- cold cranking current	156	3
- cold start performance	156	3
- conditioner	124	2
	209	3
	311	5
- current rating	156	3
- deterioration, lay-up	131	2
- fitting an 065 12V battery	220	4
- height caution	149	2
- lifters	132	2
	133	2
- management unit	123	2
- ratings	156	3
- replacing two 6v with a 12v	156	3
	220	4
- using two 12v in parallel	201	3
	218	4
- revival	36	1
- securing your batteries	111	2
- terminals, faulty	149	2
- terminal cracked	225	4
- "top hat" connectors	149	2
	198	3
- Varta's website	156	3
- vital check	111	2
Battery lifters		
- Snap-On Tools	132	2
- International Tool Co	132	2
Bulb, replacement choices	345	5
Bulb, LED replacement	301	5
Bullet connector fault	228	4
Caution, terminal clearance	149	2
Central locking, retrofit kit	253	4
Clips, wiring loom support	288	4
Cooling fans		
- Brushes, replacement	220	4
- Fault	228	4
- Oilite washer	34	1
- part numbers	34	1
- Revotec twin fan upgrade	274	4
- upgrade kit, twin fan	274	4
Cigar lighter, replacement	79	2
Cowling, steering column	123	2
Cruise control, retrofit	254	4
Door jamb switch	164	3
Daytime lighting options	340	5

MGB Workshop Notes

Daytime running lights	342	5
Fuel pump, problems		
- alternative pumps	145	2
- Bendix, replacement	145	2
- problems, lay up concerns	131	2
- relocation	144	2
	145	2
	146	2
Fuse box fault	203	3
Fuse box, faulty terminal	203	3
Fuse box overhaul	358	6
Indicators, fault	228	4
Hazard light switch fault	228	4
Headlamp relays upgrade	344	5
	349	5
Headlamps upgrade		
- upgrade	195	3
- with DRL	347re	5
- Cibie replacement units	211	3
- replacement headlamps	341	5
Headlamp, sealed beam	352	6
Heated rear window fault	228	4
Horn fault	187	3
Horn contact repair	229	4
Horn replacement	228	4
Indicator, stubborn stalks cure	312	5
Horn wiring, fire risk	189	3
Lay-up difficulties		
- batteries	131	2
Lighting history/terminology	197	3
"Lights on" alarm	194	3
	254	4
Locks, central locking retrofit	253	4
Motorola radio instructions	330	5
Overdrive stalk switch repair	242	4
Rear parking sensors	335	5
Rear wash/wipe installation	112	4
Relative visibility concerns	343	5
Relay, how does it work?	306	5
Relays in a classic car	346	5
Relay, Starter 6RA fault	305	5
Replacement starter motor		
- Standard starter motor	6	--
- Nippon Denzo	Chart	6
Reverse lamp switch	194	5
Sealed beam upgrade	195	3
Smiths' supplementary	325	5
instruments fitting instructions		
Stalk switch		
- steering column	242	3
- stubborn stalks	312	5
SU fuel pump, problems	131	2
Tailgate lamp & switch	165	3
Thatcham immobilisers	168	3
Top hat connectors		
- access panel clearance	149	2
- battery terminals	149	2
	199	3
Tow bar wiring	69	2
Turn indicators fault	228	4
Visibility of classic cars	343	5
Water pump, electric	175	3
	178	3
Windscreen wiper motor	46	1
Wiper blades		
- blade maintenance	328	5
- replacement Bosch	118	2
- replacements	118	2

Index to the whole series

Windscreen wiper box, change		
point	Chart	5
Wiring faults	228	4
Wiring loom clips	288	4
15. WHEELS & TYRES		
IMS, tyre sealant kit	237	4
Bolts, rusting solving	171	3
Metal labels, caution	234	4
Pressures for modern tyres	250	4
Space saver wheel & tyre	209	4
	241	4
Tyres		
- age replacement	163	3
- aspect ratio	113	2
- Goodyear NCT	177	3
- IMS, instant mobility systems		
or sealant	237	4
- pressures, modern tyres	250	4
- problems with tyres	234	4
- rolling radius	113	2
- replacements	163	3
- sealant, foam/mousse	237	4
- sizes	113	2
- space saver tyre	207	3
- supplier, recommended	177	3
Wheel, space saver	207	3
16. BODY		
Air dam	175	3
Air intake mesh	152	3
Air vent chamber drain tube	99	1
	275	4
Badges		
- doublesided tape	208	3
- "Jubilee" V8	332	5
Body care		
- bulkhead shelf refurb	232	4
- cleaning to concours	313	5
standard		
- corrosion, underbody	57	1
- underbody protection	119	2
- front wings	7	1
- rust	7	1
Bonnet		
- bonnet blowing up risk	268	4
	270	4
	271	4
- hinge alingment	134	2
- lock caution/risk	263	4
- louvres	94	2
- maintenance, essential	271	4
- wiring loom damage	286	4
Boot, space saver wheel	207	3
Bosch wiper blade	118	2
Bulkhead shelf refurb	232	4
Bumpers, ride height	148	2
C post, liner clips	122	2
Cills, corrosion	338	5
Clean your MGB to almost	313	5
concours standard		
Corrosion in the cills	338	5
Damp garages		
- desk top fan moves air	119	2
- Protection against damp	120	2
- Damp during winter	120	2
Door handle, internal	332	5
Door jamb switch	164	3
Drain tubes, cleaning	99	2

MGB Workshop Notes

	275	4
Front bumper, ride height	148	2
Filler cap, replacement	169	3
Fresh air vent chamber drain	98	2
	275	4
Front wheel arch panel	6	1
Front wings		
- fitting new wings	48	1
- remove & refit	6	1
- extensions	30	1
Hardtop, parts & fittings	336	5
Hinge alingnm't, bonnet	134	2
Hood (on a Roadster)		
- cleaning coffee stains	140	2
- refurbishment	140	2
- rear window, scratches	140	2
- Renovo products	141	2
- Renovo rear screen polish works!	240	4
- soft top proofing	142	2
Inner door seal screws	161	3
Intake mesh, fitting	152	3
Internal door handle, fault	332	5
Locks, rubber washers	60	2
Louvres in the bonnet	94	2
Luggage platform gas struts	319	5
Luggage rack options	255	4
Number plates, replacement	223	4
Paint codes	238	4
Paintwork, revitalising	356	6
Protection against damp	119	2
	120	2
Quarter light seal replacement	315	5
Rear parking sensors	335	5
Rear plastic window, cleaning	142	2
Renovo product range	142	2
Rust		
- body care	7	1
	8	1
- cills, corrosion	338	5
Rear bumper, ride heigbreht	148	2
Rear was/wipe installation	65	2
Rubber lock washers	60	2
Seams, rear body panels	269	4
Splashguards, front wheel arch	6	1
Spoiler, front		
- air dam	178	3
- fitting	29	1
	98	2
- LE spoiler	63	2
- sequel	71	2
Spoiler, rear (LE spoiler)	63	2
Sunvisors, replacements	331	5
Tailgate, internal light & switch	165	3
Tailgate stay assembly, spring "Ted's knob", tip	293	4
	99	2
	275	4
	317	5
	318	5
Touch up paint codes	238	4
Under bonnet felt	75	2
Visibility concerns with classic cars	343	5
Waxoyle treatment	92	2
	93	2
Webasto blow out	174	3
Webasto refurbishment	217	4
Wind noise, curing	108	2

Index to the whole series

Windscreen		
- inserts, chrome	102	2
- quaterlight seal	315	5
- replacement	102	2
Windscreen removal	212	3
Windstop	193	3
Wiper blades		
- Bosch replacement	118	2
- maintenance	328	5
17. SERVICE TOOLS		
Battery filler bottle	131	2
Battery lifter		
- Snap-On Tools	132	2
- International Tools Co	133	2
Windscreen, chrome trim tool	252	4
18. VARIOUS		
Anti-theft device, secret switch	12	1
Adhesives for the car	62	2
Badge, mounting	81	2
Battery lifter or carrier	132	2
	133	2
Belgium, registering an MGB	246	4
Dehumidifier, Winter storage	209	3
Fire extinguishers	112	2
	140	2
France, new speed laws	142	2
France, registering an MGV8	180	3
Handling		
- improvements	29	1
	98	2
- upgrade	153	3
- Upgrade Hoyle kits	185	3
Lay-up an MGBGV8	74	2
	131	2
	209	3
Luggage, fitted for an MGV8	260	4
Luggage rack options	255	4
Mobile phone, new UK law	181	3
Le Mans		
- circuit map	125	2
- planning a trip	125	2
- town map	125	2
Petrol deterioration during a lay-up	130	2
Radar detectors		
- no detectors in France!	143	2
- radar detectors	183	3
Rear window, chrome trim tool	252	4
Registering an MGB in Belgium	246	4
Registering an MGBGV8 in France		
	180	3
	188	3
Relative visibility concerns	343	5
Speed laws in France	143	2
Steering wheel locks		
- Disklock	176	3
- general	176	3
- Yellow Autolock	176	3
Underbonnet sound deadening	75	2
V8 front suspension	153	3
Window, quarter light seal	315	5
Windscreen removal	212	3
Windscreen, chrome trim tool	252	4
Wind noise, cures	108	2
Windstop	193	3

19. INTERIOR

Anti-theft		
- Eagle Claw	176	3
- Dicklock	173	3
- general	176	3
- Yellow Autolock	176	3
Air-conditioning background	87	2
Aircon installation in an MGB	279	4
Ash tray, refurbishment	355	6
Children in an MGBGTV8		
- head restraints	117	2
- seat harness	117	2
Courtesy lamp upgrade	437	12
Dashboard, walnut kits	219	4
Disklock	176	3
Dog guard, fitting	43	1
Door seal retainer strip	161	3
Eagle Claw, steering lock	176	3
Fire extinguishers		
- detailed note	140	2
- locating	112	2
- types	112	2
Fire risk, horn wiring	189	3
Gear lever gaiter, leather	204	3
Gaiter tray, walnut	219	4
Goggles, protecting sock	257	4
Hands free kits, mobile phone	181	3
Head restraints, children	117	2
Heater control valve		
- overhauling	115	2
Horn fault	229	4
	288	4
"Lights on" alarm	194	3
Luggage, fitted for an MGB	260	4
Mobile phone hands free kits	181	3
Oil can label tip	257	4
Overdrive "on" head up display	290	4
Platform, rear modification	106	2
Radio, iPod ICE modification	210	3
Rear luggage panel	106	2
Seat belt, wear danger	287	4
Seats sagging, reviving	116	2
Seats, refurbishing	248	4
Seat, upgrade	248	4
Speedometer		
- cable	1	1
Steering wheel		
- centre colour	307	5
- refurbishment	335	5
Temperature gauge		
- relocating	170	3
Walnut trim, fitting kits	219	4
Yellow Autolock	176	3
Voltmeter, adding	170	3
Wheel (steering) centre colour	307	5